

**2002 ~ 2007 XV17PC “WARRIOR” MODELS
FACTORY MODIFICATION CAMPAIGN – Pick-Up Coil
Yamaha Technical Bulletin M2007-003R**

Yamaha Motor Corporation, U.S.A. posts this notice as a service to Yamaha customers and potential Yamaha customers. Yamaha Motor Corporation, U.S.A. has decided that a defect relating to motor vehicle safety exists in all 2002 through 2007 XV17PC “Warrior” model motorcycles.

Affected Models

All 2002 XV17PCP and XV17PCPC

All 2003 XV1700RCR and XV1700RCRC

All 2004 XV17PCS and XV17PCSC

All 2005 XV17PCT and XV17PCTC

All 2006 XV17PCV, XV17PCVC, XV17PCMV, and XV17PCMVC

All 2007 XV17PCW, XV17PCWC, XV17PCMW, and XV17PCMWC

The reason for this recall: In affected motorcycles, the pick-up coil mounting bracket is not sturdy enough to prevent vibration caused by magnetic force as the pick-up rotor passes the pick-up coil, if there is too small of a clearance between them. This vibration can eventually weaken the lead wires and cause them to break. If the pick-up coil breaks while the engine is running, the engine will stall and will not restart. If this occurs while the motorcycle is being ridden, there could be an accident resulting in injury or death.

What Yamaha and your dealer will do: To correct this defect, Yamaha is initiating a Factory Modification Campaign. Affected motorcycles must have the pick-up coil replaced with a new one that has a stronger bracket and a molded protector over the lead wires to protect them from vibration. There will be no charge to you for this procedure.

What you should do now: Do not operate affected motorcycles until they are modified. If you are not the first owner of the motorcycle, and are unsure if this important modification has been done, contact any authorized Yamaha Motorcycle Dealer to check. Any authorized Yamaha Motorcycle Dealer can perform this service. For the name and location of a dealer near you, call 1-800-88-YAMAHA or visit the Dealer Locator section of this website.