

**2005 YFM125GT (Grizzly 125) and YFM125GHT (Grizzly 125 Hunter Edition)
FACTORY MODIFICATION CAMPAIGN – BRAKE REPLACEMENT
Yamaha Technical Bulletin AT2004-009**

Yamaha Motor Corporation, U.S.A. posts this notice as a service to Yamaha customers and potential Yamaha customers. Yamaha Motor Corporation, U.S.A. has decided that a defect relating to vehicle safety exists in certain 2005 YFM125GT (Grizzly 125) and YFM125GHT (Grizzly 125 Hunter Edition) ATVs. This bulletin was originally released October 1, 2004.

Affected Models

YFM125GT AE02Y-003889~004782

YFM125GHT AE02Y-004029~004678

The reason for this recall: In some of the affected vehicles, the friction material could separate from the brake shoes because of an improper adhesive-curing process during manufacture. If such separation occurs during operation, braking ability will be reduced or lost in the affected brake(s), which could cause an accident resulting in personal injury or death to the operator, other motorists, or bystanders.

What Yamaha and your dealer will do: To correct this defect, Yamaha is initiating a Factory Modification Campaign. All affected vehicles must have the front and rear brake shoes replaced with new ones. There will be no cost to the customer for this inspection/repair.

What you should do now: Vehicles that are affected should not be operated until they are modified. If you are not the first owner of the ATV and are unsure if this modification has been done, contact any authorized Yamaha Motorsports Dealer to check. Any authorized Yamaha Motorsports Dealer can perform this service. For the name and location of a dealer near you, call 1-800-88-YAMAHA or visit the Dealer Locator section of this website.