

**2006~2007 CP250 (Morphous); 2005~2007 YP400 (Majesty)  
FACTORY MODIFICATION CAMPAIGN – Fuel Pump Harness  
Yamaha Technical Bulletin M2008-002R**

Yamaha Motor Corporation, U.S.A. posts this notice as a service to Yamaha customers and potential Yamaha customers. Yamaha Motor Corporation, U.S.A. has decided a defect relating to motor vehicle safety exists in certain models of the Morphous and Majesty scooters. Yamaha Technical Bulletin M2008-002R was originally released on May 6, 2008.

<b>Affected Models</b>	<b>PID Range</b>
2006 CP250V Morphous	SG18Y-0000009~0001188
2007 CP250W Morphous	SG18Y-0001189~0001706
2005 YP400T Majesty	SH03Y-0000009~0002523
2006 YP400V Majesty	SH03Y-0002524~0004573
2007 YP400W Majesty	SH03Y-0004574~0007611

**NOTE:** Units in the affected range already modified according to the instructions in Technical Bulletin M2007-012A do not need any further modification. The modification this bulletin describes is identical to that earlier bulletin.

**The reason for this recall:** In affected scooters, the engine could stall and be difficult to restart because the wire terminals in the fuel pump wire coupler have corroded. This is because water can enter from the main wire harness and run through the harness to the fuel pump coupler. If water remains in the coupler, the terminals can become corroded, which can prevent the fuel pump from operating properly. If this corrosion affects fuel pump operation while the scooter is being ridden, there could be an accident resulting in injury or death.

**What Yamaha and your dealer will do:** To correct this defect, your authorized Yamaha dealer will install a sub-harness designed to allow water to drain before it reaches the fuel pump. If either the main wire harness connector or the fuel pump connector is corroded, it will also be replaced.

**What you should do now:** You should not ride your scooter until this important modification is performed. If you are not the first owner of the scooter and are unsure if this modification has been done, contact any authorized Yamaha Motorcycle Dealer to check. Any authorized Yamaha Motorcycle Dealer can perform this service. For the name and location of a dealer near you, call 1-800-88-YAMAHA or visit the Dealer Locator section of this website.